







Part Submission Warrant

Part Name	SLV WI	R CONN FEM		Cust. Part Number	HU5T-14489-DD			
Shown on Drawing Number		HU5T-14489)-DD	Org. Part Number		160044-0114		
Engineering Change Level			J4		Dated	2020/3/24		
Additional Engineering Changes			N/A		Dated	N/A		
Safety and/or Government Regulat	ion	✓ Yes	✓ No	Purchase Order	No. N/A	Weight (kg)0,0774		
Checking Aid Number	N/A	Checking	Aid Eng. Change L	evel	N/A	Dated N/A		
ORGANIZATION MANUFACTURII	NG INFORMA	TION		CUSTOMER SUBI	MITTAL INFORMA	TION		
Molex Incorporated - Nogales		DUN	S 812222818	Nursan				
Supplier Name & Supplier/Vendor (Code			Customer Name/Di	ivision			
Calzada Industrial Nuevo Noga Street Address	ales S/N			N/A Buyer/Buyer Code				
	nora	84094	Mexico	N/A				
		Postal Code	Country	Application				
MATERIALS REPORTING								
Has customer-required Substances	s of Concern in	formation been	reported?	J	Yes No			
Submitted by	IMDS or other	customer forma	at:		IMDS ID# 774	1887228		
Are polymeric parts identified with a	appropriate ISC	marking codes	s?	✓	Yes No	n/a		
REASON FOR SUBMISSION (Check at least one) ☐ Initial submission ☐ Change to Optional Construction or Material ☐ Engineering Change(s) ☐ Sub-Supplier or Material Source Change ☐ Tooling: Transfer, Replacement, Refurbishment, or additional ☐ Change in Part Processing ☐ Correction of Discrepancy ☐ Parts produced at Additional Location ☐ Tooling Inactive > than 1 year ☐ Other - please specify								
REQUESTED SUBMISSION LEVE Level 1 - Warrant only (and Level 2 - Warrant with prod Level 3 - Warrant with prod Level 4 - Warrant and othe Level 5 - Warrant with prod	d for designated duct samples a duct samples a r requirements	d appearance it nd limited suppo nd complete sup as defined by o	orting data submitted pporting data submit customer.	to customer.				
SUBMISSION RESULTS		_		_	_	_		
The results for dimensional These results meet all design recore Mold / Cavity / Production Process	rd requirements	_			ance criteria Explanation Require	statistical process package		
DECLARATION I affirm that the samples represented Part Approval Process Manual 4th 1920 pcs / 8 h I have noted any deviation from this EXPLANATION/COMMENTS:	Edition Require	ements. I furthe ertify that docum	r affirm that these sa		at the production ra	ate of		
_					,			
Is each Customer Tool properly tag	ged and numb	ered?	11:110:50	Yes ☐ No ☑ n,		, ,_,,		
Organization Authorized Signature		Le c	où tachiangs	40 70 12 27		ate 17-Mar-2022		
	aechtlinger		none No.	+49-7243-335-376	Fax No.	-		
Title Quality Eng	ineer	E-mail			linger@molex.c	<u>SUIII</u>		
			TOMER USE ONLY					
PPAP Warrant Disposition:	Approved	∐ Reje	ected	Other				
Customer Signature					D	ate		
Print Name			Cus	omer Tracking Numbe	r (optional)			









DATE DIVISION

2018/02/07 PLANT

Ford

SCALE

Control Plan

Prototype	Pre-launch X P	roduction			Key Contact/Pho	one				Date(Orig.)		Date (Rev.)
Control Plan Number		CP160044-0101		Rev: 8	Carl	os Ibarra	a / 52-(631) 311-	-1300 X 311-13	30		6-Oct-16	7-May-20
Part Number / Latest Chang	ge Level			See MIDAS	Core Team					Review Tear	m	
	RCPT HSG Water 160044-0114 160044-0115 160044-0116 160044-0117	HSG Short 160044-0124 160044-0125 160044-0126 160044-0127	1 1 1	SG Grommet 60044-0134 60044-0135 60044-0136 60044-0137	Matt Young,	PE; Jaro	ed Fatica, ME; N Burton, Ql	Aatt Kanniainen, E	, MIE; Jack	Carlo		Christian Martinez Manuf, Eng. , Tolano Group leader
Part Name / Description Ford 50-Way	PDB GEN 2 Recepta	cle Assembly			Supplier/Plant A	.pproval/D	Date NA			Customer Q	uality Approval/Date(I	f Req'd) NA
Supplier / Plant	ogales, Mexico Facility	y		plier Code 54-527-0444	Other Approval	Date (If R	eq'd) NA			Other Appro	oval Date (If Req'd)	NA
									Methods		1	
Part / Process Number	Process Name / Operation Description	Machine, Device Jig, Tools For Mfg.	No	Character Product	Process	Special Char. Class.	Product/Process Specification/ Tolerance	Evaluation Measurement Technique	Size	Freq.	Control Method	Reaction Plan
1 Material management & setup verification	1.0 Receive Raw material	Step process			- Receive al raw material in plant from suppliers according component drawing	No	Receive correct part number & qty	Checks pack list	100%	Each Lot received.	Procedures RRW01; RRW02 & RRW05	Hold material and report to carrier or supplier.
	1.1 Incoming Inspection			Receptacle Housing 160044-0214 160044-0224 160044-0234		No	Color Black Key "A"	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
				Receptacle Housing 160044-0215 160044-0225 160044-0235		No	Color Light Gray Key "B"	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
				Receptacle Housing 160044-0216 160044-0226 160044-0236		No	Color Dark Gray Key "C"	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.

			Receptacle Housing 160044-0217 160044-0227 160044-0237		No	Key "D"	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
			TPA 160044-0300		No	Color Natural	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
			Lever 160044-0401		No	Color Gray	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
			Pinon Gear 160044-0500		No	Color Gray	Visual	AQL	Each Lot received.	Conformance to specification record in SAP, Incoming inspection plan. Procedure Q4	Hold Material in QC hold area for disposition. Follow procedure O20, Notify supplier.
	1.2 Issue material to production order			Correct part number and quantity according work order	No	Correct raw material and qty according work order released	None	100%	Each work order	SAP system, MG01	Notify Planner & group leader
2 TPA Hopper / Bowl feed	2.0 Operator place TPA into the hopper	3105-50WAY-01			No	Correct TPA	visual	5 Pcs.	Set-Up	Work order, Drawing, Unique TPA part number used in this connector family	Reject Set-up and notify group leader
				Correct part number and quantity	No	Check TPA don't have broken ribs or lock fingers.	Vision system	100%	in process	Golden samples every set-up and shift start.	Scrap TPA
	2.1 TPA bowl vibratory operation	3105-50WAY-01		according work order	No	Check TPA don't have broken ribs or lock fingers.	Vision system	100%	in process	Golden samples every set-up and shift start.	Scrap TPA
	2.3 TPA orientation check	3105-50WAY-01			No	TPA should be oriented correctly into the housing	Vision system	100%	in process	Golden samples every set-up and shift start.	Reject / Scrap TPA
3 Pick and place TPA from in-line escapement and place onto machine pallet	3.0 Place TPA onto machine pallet	3105-50WAY-01		TPA properly seated in pallet	No	Correct postion in pallet	vision system and PLC program	100%	in process	Poke Yoke tooling design	Reject / Scrap TPA
4 TPA Standoff castle and Lock Finger presence check (bed of nails)	4.1 TPA standoff and lock finger presence check (bed of nails)	3105-50WAY-01		TPA free of damages	No	TPA must have all ribs and lock fingers.	Vision system (bed of nails)	100%	in process	Golden samples every set-up and shift start.	Scrap TPA

5 HSG Hopper / Bowl feed	5.0 Operator loads housing into hopper	3105-50WAY-01	Correct part number and quantity according work order	No	Housing should be correct part number, color and polarization key	Vision system	100%	in process	Golden samples every set-up and shift start.	Reject set-up, notify group leader
				No	Housing should be free of broken features	-	100%	in process	Golden samples every set-up and shift start.	Scrap Housing
	5.1 Bowl vibratory operation (housing)	3105-50WAY-01	Assure feed parts to machine.	No	Housing should be free of broken features	Vision system	100%	in process	Golden samples every set-up and shift start.	Scrap Housing
6 Recept hsg color check	6.1	3105-50WAY-01	Detect correct color accoding housing part number	No	Color: (Black, Lt. Gray, Dk Gray)	Color sensor	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
7 HSG polarization key inspection	7.0 HSG Polarization key inspection	3105-50WAY-01	Detect correct polarization accoding housing part number	No	Polarization (A, B, C)	Vision system	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
8 Short vs long HSG inspection	8.0 HSG inspection short Vs. Long	3105-50WAY-01	Detect correct housing version accoding housing part number	No	Short & Long	Vision system	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
9 HSG ribs presence	9.0 HSG rib presence P/N (160044-0234, - 0235, 0236 & 0237)	3105-50WAY-01	Detect housing with grommet version accoding housing part number	No	Grommet ribs on housing	Laser detection	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
10 Recept hsg pre- inspection station	10.0 to 10.2 Key options Check Polarization A, B and C and terminal fingers, cam post inspections	3105-50WAY-01	Correct housing and free of damages	No	Correct housing design / all lock fingers in place	Vision system	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
Place recept hsg onto TPA into pre-lock position	11.0 HSG placement into TPA assy'd into pre-lock position	3105-50WAY-01	TPA in pre- lock position	No	Corret TPA & position (Prelock position)	Vision system	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
12 TPA height	12.0 Correct TPA heigth	3105-50WAY-01		No	7.00 +/- 1.67	Digital indicator	5 PCs.	Set-Up	Poke Yoke tooling design	Stop process and notify group leader

13 Lever Hopper / Bowl feed	13.0 Operator loads parts into hopper	3105-50WAY-01	Correct part number, correct quantity according work order	No	Correct Part number	Visual	5 PCs.	Set-Up	Work order, Drawing, Unique LEVER part number used in this connector family	Reject Set-up and notify group leader
	13.0 Bowl vibratory operation	3105-50WAY-01	free of damages / Broken		Damaged	Visual	5 Pcs.	Set-Up	Quality Criteria	Reject Set-up and notify group leader
				No	Broken lever in lock area	Sensor	100%	Each piece during process	Golden samples every set-up and shift start.	Reject Set-up and notify group leader
Place lever onto sub- assy (recept hsg and TPA)	14.0 Proper placement of lever onto sub-assy	3105-50WAY-01	Correct assembly in to the housing	No	Free movement	Sensor	100%	in process	Golden samples every set-up and shift start.	Notify group leader, Scrap parts
Lever presence and position in pre load position check (relative to recept conn subassy)	15.0 Correct lever position check (pre-lock check)	3105-50WAY-01	Correct LEVER position ("open")	No	In correct assembly	Sensor	100%	in process	Golden samples every set-up and shift start.	Notify group leader, Scrap parts
16 Gear Hopper / Bowl feed	16.0 Operator loads parts into hopper	3105-50WAY-01	Correct part number, correct quantity according work order	No	Correct Part number	Visual	5 PCs.	Set-Up	Work order, Drawing, Unique GEAR part number used in this connector family	Reject Set-up and notify group leader
	16.1 Bowl vibratory operation	3105-50WAY-01	Assure feed	No	Gear should be free of damages	Visual	5 Pcs.	Set-Up	Quality Criteria	Reject Set-up and notify group leader
	16.2 RH & LH gear presence at escapement	3105-50WAY-01	parts to machine.	No	2 gears per connector	Sensor	100%	100%	Presence sensor, automatic stop machine	Stop process and notify group leader
17 Place of both RH and LH gears onto recept conn sub-assy	17.0 Placement of RH & LH gear	3105-50WAY-01	assembly 2 gears on housing	No	2 gears per connector	Automatic assembly process	100%	100%	Machine tool design	Stop process and notify group leader
18 Inspection of pinion gears (LH and RH)	18.0 Pinion gear position and presence on receptacle sub-assy (LH and RH)	3105-50WAY-01	assembly 2 gears on housing	No	Correct position of gears on housing and no missing gears	Sensors	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader
Position cam lever into final position (shipping position)	19.0 Move/rotate lever into final position (shipping position)	3105-50WAY-01	Engage LEVER and GEAR	No	Gear and Lever should need to rotate easy, no stuck.	Automatic assembly process	100%	in process	Machine tool design, rotatory devise	Stop process and notify group leader

20 Final Inspection Station	20.0 to 20.2 Lever Present & Position, gear presence, TPA in pre-lock Inspect,	3105-50WAY-01	Free of damages and missing components	No	No missing components in connector	Vision system	100%	in process	Golden samples every set-up and shift start.	Stop process and notify group leader / scrap connectors
21 Keyence laser date code of recept sub-assy	21.0 Laser marking (only good parts)	3105-50WAY-01	Mark parts with customer part number, julian date code and shifth code.	No	Correct and human readable information on laser mark & complete characters (each connector part number)	Visual	5 PCs.	Set-Up	work order, inspection plan, drawing	Stop process and notify group leader / scrap connectors
Move the assy to the P&P station	22.0 Move the assy to the P&P station	3105-50WAY-01	Put a piece in P&P area	No	Correct position	sensor	100%	in process	PLC program	Stop process and notify group leader.
23 P&P finish goods	23.0 Unload non- conformant assembly into the reject bin (rejections due to lever issues must be manually)	3105-50WAY-01	Put rejected part in red bin	No	Reject bad parts	Automatic assembly process	100%	in process	Quality Criteria, machine program, golden samples	Stop process and notify group leader.
24 Empty nest check	24.0 Empty nest check	3105-50WAY-01	Empty nest available	No	Nest free of parts	Sensor	100%	in process	PLC program	Stop process and notify group leader.
25 Pallet transfer (return)	25.0 Unload good assembly into the conveyor and part blow-off.	3105-50WAY-01	Take parts out from nest	No	Take parts correctly from nest	Automatic assembly process	100%	in process	PLC program and machine gripper design	Stop process and notify group leader.
	25.1 Pallet transfer (return)	3105-50WAY-01	Empty nest available	No	Process step					
26 Good assy transfer & packing	26.0 "GOOD" Assembly's transfer to the autopacking system	3105-50WAY-01	unload good parts	No	Take parts correctly from nest	Automatic assembly process	100%	in process	PLC program and machine gripper design	Stop process and notify group leader / scrap connectors
	26.1 Auto unload the connector assy into packaging tray	3105-50WAY-01	Correct quantity	No	24 connectors per tray.	Automatic assembly process		in process	Drawing PK-31302-351	Stop process and notify group leader.
27 Final inspection	27.0 Final Inspection		Inspect parts for cosmetic issues	No	No damaged, no missing components, correct assembly	Visual	100%	100%	Quality criterias	Scrap defective parts
28 QC Audit	28.0 Q. C. Audit		Inspect parts for cosmetic issues	No	No damaged, no missing components, correct assembly	Visual	10%	Each box / tray	Quality criterias	reject suspect tray / box, follow O20 Procedure

29 Packing & labeling	29.0 Place fully loaded trays into the box (4) & stick the manufacturing label	load correct qty of tays per box	No	4 trays per box (24 parts per tray and 96 Pcs. Per box, correct ID label on box)		100%	tray	Drawing PK- 31302-351,	reject suspect tray / box, follow O20 Procedure
	manufacturing facer		No	All trays to be orientated in the same direction in each box	Visual	100%	Each box / tray	Visual inspection and conformances PK-31302-351	reject suspect tray / box, follow O20 Procedure
30 Weight station	30.0 Weight station	Weigth boxes	No	96 Pcs. Per box,	Weight	100%	Each box	Drawing Pk-31302-351	reject suspect box, follow O20 Procedure
31 Storage	31.0 Send FG to warehouse	Correct part number and quantity.	No	Assure correct storage location and easy localization	SAP & Visual	100%	Each box.	SAP system, Work instruction W117	Stop Process, report issues to Q.C. Eng. & Warehouse supervisor
		Free of box damages	No	No damaged boxes	Visual	100%	Each Box	Warehouse personel trainning	Stop Process, report issues to Q.C. Eng. & Warehouse supervisor
32 Shipping	32.0 Ship to customer	Correct part number and quantity accodring customer order	No	Send correct assemblies part number, correct qty, on time	SAP reports	100%	each shipment	SAP reports (customer orders) work instruction W101	Stop Process, report issues to Q.C. Eng. & Warehouse supervisor

Rev	Date	Originator	Comments
1	13-Sep-16	Burton	Initial Draft - Pre review with team and Carlos
2	21-Sep-16	Burton / Ibarra	Plant review confirmation
3	29-Sep-16	Burton / Ibarra	Plant review confirmation
		_	
4	20-Apr-17	Ibarra	Review C.P. to assure it match with inspection plan and process
		C. Ibarra	
5	29-Nov-18	J. Rios	Review C.P. and add new assemby part numbers
6		C. Ibarra	
Ů	22-Mar-19	J. Rios	Review C.P. to assure it match with FMEA & flow chart
		C. Ibarra	
7	10/23/2019	O. Reyes	Review C.P. per LPA audit
		C. Ibarra	
8	5/7/2020	C. Martinez	Review and add a new failure mode "broken lever in lock area" in step # 13



Molex Initial Sample Inspection Report Quality Control

							CTOR: aciano			DATE: 3-Mar-2022			
	Drawing #: HU5T-14489-DD REV: J4 2020/3/24 VENDOR: MOLEX Molex P/N: 160044-0114 Ford P/N: HU5T-14489-DD												
No.	PRI Nominal	NT S	SPEC. Tolera	nco	Sample 1	Actual Measurements					UNITS	GAGE#	LEGEND
1	42.20	+	0.60	- 0.60	42.065	Sample 2 42.063	Sample 3 42.090	Sample 4 42.062	Sample 5 42.094	Sample 6 42.093	MM	I-011	1
2	132.22	+	0.80	- 0.80	132.150	132.151	132.141	132.083	132.168	132.155	MM	CMM-003	1
3	7.00	+	2.00	- 2.00	7.042	7.175	7.231	7.137	7.093	7.075	MM	I-011	1
4	50.90	+	0.20	- 0.50	50.684	50.705	50.707	50.708	50.711	50.687	MM	I-011	1
5	Housing (Color	" BLAC	K "	OK	OK	OK	OK	OK	OK			VISUAL
6	TPA Colo	or "N	IATURAL	. "	OK	OK	OK	OK	OK	OK			VISUAL
7	Circu	it Siz	ze " 50 "		OK	OK	OK	OK	OK	OK			VISUAL
8			t (kg)		0.0774								
9	Notes:	1,2,3	3,4,5,6,7,	8	OK REVIEWED	OK REVIEWED	OK REVIEWED	OK REVIEWED	OK REVIEWED	OK REVIEWED			

DIMENSION "OUT OF TOLERANCE"

MARKED THUS "X"

- 1 Accepted
- Rejected
- Conditional
- Tool life QCC.

Assy part 1600440114

1600440214 PDB GEN2 HSNG RCPT 50CKT WATER BLK POL A (0899921706)

1600440300 PDB TPA RCPT 50CKT NAT (0899921447)

1600440401 PDB GEN2 LEVER (0899922128)

1600440500 PDB PINION GEAR LIGHT GRAY (0899922128)



Certificate of Analysis

Customer:

Attention:

Cust Prod:

FAX:

Product Number

: 50155020

Product Name

: ULTRAMID® A3EG7 HP BK23189

POLYAMIDE 726KG Fibreboard IBC

MOLEX LLC

1400 W BOND CIR LINCOLN NE 68521-3696 Vehicle

: WF2005091

Batch/Lot Manuf.Date

: Jan-05-2022

Shipped Date

Shipped Quantity

: 1,452.000 KG

0899921706

Delivery Date

: Mar-01-2022

Cust Prod Name:

ULT.A3EG7 HP BK23189 726KG 11G

Order Number

: 118591592 000010

Cust P.O.: Cust P.O. Line: 1008595006

10

Delivery Note

146286342 900001

Inspection Certificate 3.1 according to EN 10204

Inspection Certificate 3.1 according to EN 10204			Specifi	cation		
Characteristic	Result	UOM	Minimum	Maximum	Test Method	
Ash / Filler Content Moisture Content Viscosity Number for Polyamides	34,667 0.03 131	% % ml/g	33.000 120		ASTM5630/ISO3451 ASTM D6869 / ISO 15512B ISO 307	

The above results are the means of individual test values determined on samples taken during production of the lot specified.

This product is approved to the following specifications:

WSS-M4D673-B1

M53122

Page 1 of 1



3000 Town Center, Suite 2820,,Southfield,MI 48075 USA, TEL: 248-355-9590 FAX: 248-355-9330

Certificate of Analysis

To whom it may concern

We hereby certify that the following commodity has been tested by us and its quality corresponds to the description as mentioned below.

Product Name/Grade/Color No./Package	Xarec N WA 7030-02 Natural 740KG						
Lot No.	KK0501QCJ1	Lot Size	2,220.000 kg				
Customer Part No.	899921447	Delivery Date	02/22/2022				
PO No.	1008736030	Sales Order	1100014982				
Customer Name	Molex						

Properties	Testing Method	Unit	Specification	Test Result
Ash Content	ISO 3451-1A	%	28.00 - 32.00	29.9
Tensile Strength, Break	ISO 527,	MPa	> 125.00	175.00
Tensile Elongation,Break	ISO 527,	%	> 1.60	3.0
Melt Viscosity T5, 400sec-1	DOWN 101821	Pascal sec	59.00 - 235.00	173.00
Melt Viscosity T10, 400sec-1	DOWN 101821		45.00 - 176.00	136.00

Idemitsu Chemicals U.S.A. Corporation

Date: 02/16/2022

Ryowke Lordo

MOLEX LLC



Certificate of Analysis

Customer: Product Number : 50513537

Product Name : ULTRAMID*A3EG10 GREY 22906

POLYAMIDE 726KG Fibreboard IBC

700 UPLAND Vehicle : X11114 LINCOLN NE 68521-0000

 Batch/Lot
 : 0210155133

 Manuf.Date
 : Dec-16-2021

 Shipped Date
 : Feb-01-2022

Attention: MOLDINGCOA@MOLEX.COM Shipped Date : Feb-01-2022 eMAIL: moldingcoa@molex.com Shipped Quantity : 1,452.000 KG Cust Prod: 0899922128 Delivery Date : Feb-03-2022 Cust Prod Name: ULT.A3EG10 GR22906 726KG 11G Order Number : 118526111 000010

Cust P.O.: 1008392428

Cust P.O. Line: 10 Delivery Note : 146214933 900001

Inspection Certificate 3.1 according to EN 10204

----Specification-----UOM Characteristic Result Minimum Maximum Test Method Ash / Filler Content 50.58 52.00 % 48.00 ASTM5630/ISO3451 Moisture Content 0.02 0.15 ASTM D6869 / ISO 15512B Viscosity Number for Polyamides 132 ml/g 120 150 ISO 307

Comments:

The data shown is the results of tests performed on the lot specified.

Page 1 of 1

The information contained herein is based either on analytical tests of samples or on statistical process data; it is intended solely for purposes of comparison with the established specifications for the product. Warranties of the product are exclusively as set forth in the applicable contract documents.