

PROCESS FLOW DIAGRAM

Part Certificatio

Tait Certification		
Family name: AUTOMATIC ASSEMBLY	Date (Orig.) 30-Oct-2021	Prepared by: SIBAMEA, PEDRO N
Part Number: (Delphi:15425692)	Date (Rev.) 30-Oct-2021	Title: INDUSTRIAL ENGINEER PLANT 9800 CENTEC 1
Part Name: (Delphi:ASM CONN 4 F APEX 2.8 BLK SLD)	Page 1	Phone Number +52 844 4115500
Cross Functional team Members CHAVARRIA, VICTOR +52 844 4115500GARZA, RAQUELINE V +52 844 4115500RAMIREZ, FABIAN HORACIC EDUARDO 86-63-400 ext 5420ORTIZ URIBE, DIEGO A. 3480DOMINGUEZ, SALOME +52SIBAMEA, PEDRO N 844 4115500GARCIA, ABRIL +52 844 4115500MACIAS, MARCO +52 844 4115500ZARTUCHE, LUIS nullSANO	+52 844 4115500GARCIA, ABRIL	Symbol Key: +52 ◆ Manufacturing/Assembly • Movement of Materials/Parts ▲ Storage of Materials/Parts ■ Inspection
Sten # Fab Move Store Insp		Item# Special Characteristics

					Storage of Materials/Parts Inspection		
Step #	Fab	Move	Store	Insp	Operation description	Item #	Special Characteristics
10		•			RECEIVING MATERIAL IN DOCKS		
20					VISUAL INSPECTION OF MATERIAL RECEIVED TO VERIFY PHYSICAL CONTAINER CONDITION AND COMPARE AGAINST MANIFEST		
25					CHECK OF THE AMOUNT OF RAW MATERIAL IN PARTS UNIQUE BOUGHT		
30	•				LOAD MATERIAL IN SYSTEM (SAP/QAS)		
40		•			MOVE MATERIAL FROM RAMP TO SUPERMARKET AREA OR MATERIAL SUSPECT/ UNDER QUALITY ALERT TO INCOMING INSPECTION		
41		•			MOVE MATERIAL SUSPECT OR UNDER QUALITY ALERT TO INCOMING INSPECTION AREA		
42				•	MATERIAL ARE INSPECTED IN INCOMING INSPECTION AREA		
43		•			MATERIAL INSPECTED IS MOVED RAMPS OR MNC IS SCRAPED OR RETURNED TO THE SUPPLIER		
50			•		STORE MATERIAL IN SUPERMARKET / SHOP STOCK AREA		
60	•				PRINT SHIPPING LABELS AND PROCESS CARD ACCORDING TO THE REQUERIMENTS		
70		•			MOVE SHIPPING LABELS TO WORK STATION (WHEN APPLY)		
80	•				BUILD THE KIT ACCORDING TO THE REQUIREMENTS (WHEN APPLY)		
85	*				TO REQUEST SHIPPING LABEL FROM KIT PART NUMBER (WHEN APPLY)		
90		•			MOVE MATERIAL, AND TOOL FROM KIT'S CENTER TO WORK STATION ACCORDING TO THE REQUIREMENTS (WHEN APPLY)		
100		•			MOVE MATERIAL, PACKING MATERIAL AND TOOL OF THE P/N CHANGE FROM WORK STATION TO KIT'S CENTER OR PACKING CAR (WHEN APPLY)		
105	•				TRANSFER MATERIAL FROM SUPERMARKET AND SHOP STOCK SLOCK (SLOCK 1) TO WIP SLOCK (SLOCK 2) IN SAP/QAS SYSTEM (SCANNING)		
110		•			MOVE COMPONENT FROM SUPERMARKET, PARTS PURCHASED SHOP STOCK AND MOLDING SHOP STOCK AREA TO WORK STATION		
140		•			MOVE BOXES, RETURNABLE CONTAINERS FROM SUPERMARKET AREA TO WORK STATION		
145		•			MOVE FINISHED GOOD FROM INCOMPLETE CONTAINER AREA TO WORK STATION (WHEN APPLY)		
150					VERIFICATION OF SET-UP BY MANUFACTURING (LOAD RIGHT ROW MATERIAL FOR RUN PART NUMBER)		
160	•				PLACE SHIPPING LABEL ON CONTAINER/BOX		
162	•			-	SCANING, PROCESS CARD, TOOL NEST,COMPONENTS. ID OPERATOR AND SHIPPING LABEL.		
180	•				ASSEMBLY CABLE.SEAL ON RETAINER IN THE TURN TABLE		
190	•			•	ASSEMBLY CONNECTOR ON CABLE.SEAL, RETAINER IN THE TURN TABLE		
195	•				MARK PRINT (JULLIAN DATE)		
200	•			•	ASSEMBLY SEAL ON CONNECTOR, CABLE.SEAL, RETAINER IN THE TURN TABLE		
210	•			•	ASSEMBLY CPA ON CONNECTOR, SEAL, CABLE SEAL, RETAINER ON TURN TABLE		
220	•			•	ASSEMBLY PLR ON CONNECTOR, SEAL, CABLE SEAL, RETAINER, CPA ON TURN TABLE		
290	•			•	FIRST SAMPLE RELEASED BY Q.C. PROCESS AUDIT BY Q.C.		
310	•				FINISH ASSEMBLY IS PACKAGED BAG IS CLOSED		
316		•			MOVE FINISH GOOD CONTAINER FROM WORK STATION TO INCOMPLETE CONTAINER AREA (WHEN APPLY)		
318	•				RELABELING WHEN APPLY		
320		•			FINISHED GOOD CONTAINERS ARE MOVED TO MANUFACTURING INSPECTION AREA WHEN APPLY		
325					VERIFICATION OF SET-UP IN MANUFACTURING INSPECTION AREA		
330				•	MANUFACTURING INSPECTION (CONTAINMENT IS APPLIED WHEN APPLY)		
340		•			MOVE FINISH GOOD CONTAINER TO Q.C. INSPECTION AREA WHEN APPLY		
351					AUDIT PRODUCTS OF FINAL ASSEMBLY		
352				•	INSPECTION LAY OUT ANNUAL		
370	•				CONTAINER IS CLOSED		
380		•			MOVE FINISH GOOD CONTAINERS TO SHIPPING AREA.		
390	•				FINISH GOOD CONTAINERS ARE SEGREGATED BY DESTINATION		
400	•				MANIFEST (PUSH DELIVERY) IS ELABORATED		

_								
	Step #	Fab	Move	Store	Insp	Operation description	Item #	Special Characteristics
Г	410		•			MOVE FINISH GOOD CONTAINERS FROM SHIPPING AREA TO DISTRIBUTION CENTER		