

文件编号: FC-033472-AA017

料号: 33472****&1600**

文件名称: MX150 2X*Rec flexible line Assembly Process

版本: REV.: G


页码:

1/1

步骤

流程图

备注



变更内容

变更者

制作

核对

审核

D	2017-09-14	Feeder Bowl load TPA to track automatically						Wu Ryan	Fanny & Chen chao	Lv, Fang
E	2017-12-12	Add "Transmission" part number and step16.0"sensor check CAP color"						Felix Yang	Fanny & Chenchao	Lv, Fang
F	2021-03-18	update load component to track and "29.0 IPQC to FQC"						Zhou Jianping	Xie Pei	He Bin
G	2021-08-20	A033472D/E/F/G/H文件共用,CAP颜色检测为 (Option) 可选.						Lv Yong	Xie Pei	Hu Xin
分发范围:	CBU Assembly	x份	EBU Assembly	x份	TBU Assembly	6份	Insert molding	x份		
	Molding	x份	Plating	x份	Stamping	x份	Other	x份		